



Republic of the Philippines
DEPARTMENT OF EDUCATION
 Region VII, Central Visayas
SCHOOLS DIVISION OF NEGROS ORIENTAL
 www.depednegor.net

DepED Neg. OR.
RELEASED
 No.: 017.3447
 DATE: 26 NOV 2018
 BY: [Signature]
 RECORDS SECTION

November 26, 2018

TRAVEL ORDER
 No. 1401 s. 2018

To : **JOSEPH R. GEMINA**
 Project Development Officer II - DRRM

Purpose : To conduct ocular inspection in the following schools:

- **MATAMBOK ELEMENTARY SCHOOL**
 Brgy. Mandalupang, Manjuyod Negros Oriental
- **AGUTAYON PRIMARY SCHOOL**
 Jimalalud, Negros Oriental

Date / Place/Venue: November 28, 2018 – Manjuyod, Negros Oriental
 November 29, 2018 – Jimalalud, Negros Oriental

ALLOWED/CHARGED TO: (School MOOE, subject to the usual accounting and auditing rules and regulations)

- _____ : Registration
- _____ : Transportation
- _____ : Board and Lodging
- _____ : Meals
- : Transportation & other incidental expenses

for: [Signature]
WILFREDA D. BONGALOS, Ph. D., CESO V
 Schools Division Superintendent [Signature]



PHILIPPINE NATIONAL POLICE
MANJUYOD POLICE STATION
 Manjuyod, Negros Oriental
 Email add: > manjuyodpolice@yahoo.com



EXTRACT COPY

DATE: November 22, 2018
TIME: 4:30 pm
ENTRY NR: 11080

"FALLING ROCK THAT RESULTED TO DAMAGE"

Place of Incident: So. Matambok, Brgy. Mandalupang Manjuyod, Negros Oriental
Time/Date: November 22, 2018
Reporter/Teacher : Fletcher B. Acab, male, 39 yrs. old, married, School DRRM Coordinator and a resident of Brgy. Suba, Manjuyod, Negros Oriental.

Damage : Dne classroom, One Bookshelf, One Desk anr whole window and also slightly damage the wall of the said classroom.

Facts : Ang usa, ka classroom sa Matambok Elementary School, nalimbagan ug usa kadakong bato sa tunga tunga ng area sa mge alas 9:00 ug 7:00 sa buntag niadtung novembre 21, 2018. For record.

REC. BY: SPO1 ROLLYBEN R. PAYPA, PNP


CERTIFICATION

TO WHOM IT MAY CONCERN:

THIS IS TO CERTIFY that the above EXTRACT COPY taken from the Police Blotter on page **272** entry nr **11080** dated **November 22, 2018** as recorded by **SPO1 ROLLYBEN R. PAYPA, PNP**.

This certification is issued for whatever legal purpose it may deem necessary.

ISSUED this **22th** day of **November 2018**, at Manjuyod, Oriental Negros, Philippines.


PSI ANTONIO F JABAR
 Acting Chief of Police

Republic of the Philippines
Province of Negros Oriental
Municipality of Jimalalud

MUNICIPAL DISASTER RISK REDUCTION MANAGEMENT OFFICE

SPECIAL REPORT ON THE OCULAR INSPECTION IN BARANGAY AGUTAYON ON OCTOBER 17, 2018

The MDRRMO Office of the Municipality of Jimalalud received a text message last October 15, 2018 regarding a possible landslide in the said barangay. The office under its MDRRMO sent a personnel in the area to conduct an immediate inspection to see the possible damages caused by the landslide. Upon reaching the area, said personnel assessed the gravity of the situation, took pictures and interviewed residents around the area. It was agreed that the area will be inspected by the DRRMO of the Municipality of Jimalalud, Mr. Carlos M. Serillo, Jr. and the Municipal Engineer, Engr. Joseph Jerome M. Jayme.

The second team, led by the MDRRMO and the Mun. Engineer visited the site on October 17, 2018.

The area of the landslide in Barangay Agutayon is in Sitio Proper beside its Primary School. It is around 20-25 meters from its building. The diameter of the landslide [is more or less 6 meters. The soil in the landslide area is made of sandy clay causing an immediate landslide after a heavy downpour the night before. It created a certain path that if there is a possibility of a landslide happening again, the school in the area will be in its path making it unsafe and dangerous to the people and students.

According to Engr. Jayme and Mr. Serillo, Jr., there is a need to relocate the school since it is no longer safe for the students and teachers. It is also impossible to construct an infrastructure to protect the school building since it is near a cliff.


This report is intended to inform the Department of Education to address the issue on possible relocation of the Agutayon Primary Scholl as soon as possible to prevent major damage and possible loss of lives in case of heavy downpour and landslide.

Photos on the landslide area will be attached in this report to support the views and recommendations of the inspecting team.

Prepared by:


CARLOS M. SERILLO JR.
MDRRMO II

Attested by:


Engr. JOSEPH JEROME M. JAYME
MEC
